
LINE
PLUG AC
GND
NEUTRAL
Power Switch
MAIN FUSE
Voltage Selector
240v
220v
200v
115v
0v
Power Tube
Plate Winding
Bias Winding
Filament Winding
BEFORE


DISCONNECT THE LINE FROM THE FUSE TO THE VOLTAGE SELECTOR AND DISCONNECT THE 240V LINE FROM THE VOLTAGE SELECTOR TO THE TRANSFORMER.
HARDWIRE FROM THE FUSE TO THE 240V LINE OF THE TRANSFORMER.
LINE
PLUG AC
GND
NEUTRAL
Power Switch
MAIN FUSE
Voltage Selector
DISCONNECT THE 115V LINE FROM THE VOLTAGE SELECTOR AND HARDWIRE IT TO THE NEUTRAL SIDE OF THE POWER SWITCH
125v
240v
NEW VOLTAGES
APPEAR IN RED
220v
200v
0v
115v
0v
CAP OFF WITH TAPE OR A WIRE NUT
Power Tube
Plate Winding
Bias Winding
Filament Winding
AFTER